

# Operating Instruction (TPM-10)

## Features

- LCD display
- Insert design
- Simple appearance
- Two button batteries for longer use time
- Especially applied in refrigerator, chiller, deepfreeze etc.

## Technical parameter

- Temperature range:  $-50^{\circ}\text{C}\sim+110^{\circ}\text{C}$
- Using environment: Temperature:  $-5^{\circ}\text{C}\sim+50^{\circ}\text{C}$   
Humidity:  $5\%\sim 80\%$
- Accuracy:  $\pm 1^{\circ}\text{C}$
- Resolution: 0.1
- Power: two button battery (LR44, 1.5v)

## Instruction

- Open the battery cover to put in two LR44 batteries correctly, pay attention to the polarity.
- Display when put in the batteries. Pls take out the batteries when not use for long time
- LCD display  $\text{H}^{\circ}\text{C}$  when temperature is higher than  $110^{\circ}\text{C}$   
LCD display  $\text{L}^{\circ}\text{C}$  when temperature is lower than  $-50^{\circ}\text{C}$ .
- Insert size: 46 x 26.6mm